25X1A		
`	Approved For Release 2002/06/47-1014 RDP78B04747A001500030076-0	25X1A
` `` ,		
25X1A	#1382 26 September 1967	
25X1A _.	Contracting Officer Post Office Box 6788 Fort Davis Station Washington, D. C. 20020	
25X1A	Subject: Request for Funding	
	As a result of the activities of this contract, r in close coordination with the technical representatives of your organization over the past several months, and the meeting held at your facility on the same subject on 7 September 1967, submits herewith a request for funding to accomplish further effort on the subject contract and to accomplish added tasks to improve the systems.	25X1A
25X1A	We have divided the funding request into several individual parts with supporting cost sheets for each. The overrun funding request attached hereto is for the full amount estimated to accomplish the overrun tasks. This contractor understands that the actual contractual funding will be only 75% of that shown. The request for added task funds is made using overhead and G & A rates as covered by the negotiations under subject contract, i.e., a fixed overhead rate of and a G & A rate of 25%. The alignment microscope and training program are separate and distinct (and in the case of the microscope involves commercial products); these are being submitted at our current rates rather than the fixed contractual rates.	
	The request for funding, as applicable to the 405B machine, is covered in Exhibit "A" for the accomplishment of the following tasks on the five machines as originally delivered under subject contract. Our activities will be to fabricate and install in three separate operations, i.e., accomplishment on the first two 405 machines presently at DECLASS REVIEW by NIMA/DOD	

Received 30ct 1961

CONFIDENTIAL

GROUP T
EXCLUDED 1730 AUTOMATIC
DOWNGRADING AND
DEGLASSIFICATION

25X1A

#1382

-2-

26 September 1967

our facility, on another group of two machines to be delivered to these facilities upon acceptance of the first two, and thirdly, to be accomplished on the last machine at the same time they are accomplished on the 405AM machine after the delivery of the second two 405B machines.

The overrun tasks to be accomplished are as follows:

- a. Fabricate new mounting mechanisms for improved operation of negator.springs.
 - b. Redesign of the curtain assembly for improved operation.
- c. Reduce warm-up time (ready light) for power turn-off (inadvertent) to minimize stabilizing time rather than full 45 minute warm-up upon initial turn-on.
- d. Replacement of nameplate on front panel from 3/8 amp to 3/4 amp.
- e. Update manual of operating procedures to the equipment's latest configuration.
- f. Update drawings as provided by the contract to depict final configuration.

The following added tasks, applicable to the 405B machines, are herewith provided with cost analyses noted below.

Exhibit "B" covers the following added tasks.

- a. Modification of the head rest structure for improved support.
- b. Providing an access cover for ventilation and viewing of the pump assembly (water level).
- c. Access cover in machine sheet metal cover for adjustment of X exis interferometer.
- d. Access cover in sheet metal cover and headrest support for adjustment of Y axis interferometer.
- e. Wiring and placement of test points on front panel of digitizer for checking voltage level on Schmitt trigger circuits. This

25X1A

#1382

-3-

26 September 1967

requires relocation of high voltage potentiometers to the front panel. Study has shown that the high voltage potentiometer value and resolution are correct as designed, and we recommend no change.

f. Installation of chassis guide rails for easier access to both digitizer chasses.

Exhibit "C" covers the cost of adding a knee guide to the center opening of the 405B machines to prevent the operator's knees from touching the working table.

Exhibit "D" covers supplying of an alignment microscope which can be used with any of the interferometers provided on the 405B or 405A contracts. This microscope is used to align the interferometers with the basic working tables. It is an item which is also offered as an option to our commercial interferometer customers.

Exhibit "E" covers the cost for conducting a training program at our facility for your calibration and maintenance personnel.

A description of the training program is contained in Exhibit ¹⁷F". It is our suggestion that this training program be conducted during the system test phase when the second two 405 machines are modified and assembled in our plant.

Exhibit "G" contains a list of our recommended spare parts for maintaining both the 405B and 405AM machines, with unit prices and totals applicable to quantity recommended.

Exhibits "H-1" and "H-2" cover costs to modify the 405AM machine to make it equal to the 405B machines with the added tasks as recommended above. (Exhibits H-1 and H-2 relate respectively to Exhibits B and C.) In addition to the added tasks as described above, the following tasks will also be accomplished.

- a. Modification of the microscope focus mechanisms equivalent to the 405B to provide improved reliability and minimize backlash. If a new design is desired, a separate quotation will be prepared.
- b. Modification of the general illumination to improve the cut-off of the light on the chip format.

It should be pointed out that the spare parts list, the alignment microscope, and the training program suggested above are equally applicable to the 405AM.

Approved For Release 2002/06/17 CIARDP78B04747A001500030076-0

5X1A	<u></u> 41382	-4-	26 September 1967		
	Certain of the added tasks described above are presently being accomplished on the two 405B machines in our possession, and some of these added tasks have already been installed on the 405AM machine. The remaining tasks on the 405AM will be accomplished upon its return to our facility. It is our understanding that these actions are essential to the proper utilization of the equipment by your personnel, and we have accordingly taken this action in the best interests of both parties. As pointed out above, action to improve the equipment has already been instituted. Your expeditious review of our funding request herein will be appreciated. If we can provide you with any additional				
	information or expan	d on that provided herei	n, please do not hesitate	to	
		Very	truly yours,	, .	
				25X1A	
		ORIG	SINAL SIGNED BY		
	· · ·			25X1A	
	LHB/aw Encs.				
5X1A	cc:				

COMPLETE

BEST COPY Available

Next 10 Page(s) In Document Exempt

Approved For Release 2002/06/17: CIA-RDP78B04747A001500030076-0

I the reason for selecting the two 405 B's

that went book to was in the process of moving them two

machines and the final intellation point

room was not get in condition to

have the instruments placed in them.

2. PAG can only have one markine installed at the present time because of the ficility difficultie

3,

A menumetion accuracy analysis will have to be performed on the chip comparator and TID is the obvious place to perform this study